

**GOVERNMENT OF ANDHRA PRADESH
ROADS AND BUILDINGS DEPARTMENT**

From,
Sri.Y.V.Kishore Babuji. B.Tech,
Executive Engineer (R&B
(R&B) Division, Eluru,

To,
The Head Master,
ST.Lucy E.M High School,
Janampeta Village,
Pedavgi Mandal,
Eluru District.

Lr.No:259/Soundness Certificate/JA/2020

Dt: 06/10/2026.

Sir,


Sub:- Works (R&B) Division, Eluru - ST.Lucy E.M High School, Janampeta Village,
Pedavgi Mandal, in Eluru District. - Soundness Certificate - Issued- Regarding.

Ref: -1. Your Lr.No.Nill, Dated: 28.09.2026.

2. Letter.No. ST.L.E.M.H.Scl/S.Certificate/H.C/2026 Dt: 03.10.2026.
of the Deputy Executive Engineer (R&B) No.ISub-Division Eluru.

With reference to above, it is informed that as per the request of Correspondent dated 03.10.2026 the RCC Roof Building Ground floor. 1st floor & 2nd floor ST.Lucy E.M High School, Janampeta Village, Pedavgi Mandal, in Eluru District. was inspected and it is structurally sound to run the classes for a period of One year (i.e.) from 03.10.2026 to 02.10.2027.
Enclose: Soundness Certificate.

Yours faithfully,


Executive Engineer
(R&B) Division, Eluru.


SOUNDNESS CERTIFICATE


	Name of the School & Address	:	The ST.Lucy English Medium High School, mariapuram, (V) Janampet, Vijayarai Pedavegi (M) in Eluru District.
	Name of the Management and phone Number	:	6281167510
	Date of Inspection	:	A.E.E :
	Date of Inspection	:	D.E.E : 03-10-2026
1	Year of construction	:	2000
2	Type of the building	:	RCC Roof Building Ground Floor, 1 st floor & 2 nd floor
3	Type of foundation footings, Basement and Plinth beam etc	:	Foundation as shown in drawing
4	Present condition of foundation whether any settlement cracks are observed upto basement level	:	Sound
5	Soundness of superstructure whether any cracks out of plumb in walls noticed	:	Sound
6	Soundness of RCC beam and lintels over openings	:	Sound
7	Condition of flooring	:	Sound
8	Condition of roof slabs, staircase slabs, cracks, leakages	:	Sound
9	The structure of Building sound and Stability Certificate is issued for one Year	:	From 03-10-2026 To 02-10-2027
10	Any other remarks which are required to ensure the structural soundness	:	This inspection certificate does not purport covering all the aspects of the work & Designs.


CERTIFICATE

- 1) Certificate is issued based on the present physical condition of the building. The management is responsible for the structure deformities which occur during course of time in future
- 2) Further the management has to take necessary precautions during natural calamities occur from time to time for the safety of the students. (Such as cyclones severe weather conditions, Tsunamis, earth quakes etc.)
- 3) Department is not responsible for any structural changes to the building in future course of time.

CERTIFICATE :

I do here by certify that I have inspected the school and found to structurally sound for running the School as the building is fit for the purpose of providing shelter from sun and rain.


Deputy Executive Engineer (R&B)
No.2 Sub - Division, Eluru.


Executive Engineer (R&B)
Division, Eluru.

6/10/2026